JOB NO :013-22-000002 Replacement of burnt bulbs ... Mallasandra

BRUHAT BENGALURU MAHANAGARA PALIKE

EXECUTIVE ENGINEER (ELECRICALS) DASARAHALLI ZONE

Monthly Consolidated Statement of street Lihts Maintenance Complaints for the month Of

Package No: D - 13

Ward No: 13

Name Of The Contractor

Sr.No	Date	No Of Complaints received	No Of Complaints Atteneded	No Of Pending Complaints	36/40 W fluorescent tube ligh	125W HPMV	250W HPSV	400 watts HPSV	24 Watt to 40 Watt LED	40 Watt to 65 W LED street Light	90W LED street light	Remarks
1	01/11/2022	15	15	—	—	4	3	1	—	3	4	
2	02/11/2022	15	15	—	—	2	6	—	2	1	4	
3	03/11/2022	15	15	—	—	3	5	—	1	3	3	
4	04/11/2022	15	15	—	—	2	6	—	—	2	5	
5	05/11/2022	15	15	—	—	3	4	—	—	3	5	
6	07/11/2022	15	15	—	—	1	4	2	2	4	2	
7	08/11/2022	15	15	—	—	2	3	5	1	2	3	
8	09/11/2022	15	15	—	—	—	4	4	1	2	4	
9	10/11/2022	15	15	—	—	4	6	—	2	3	—	
10	11/11/2022	15	15	—	—	3	6	—	3	2	1	
11	12/11/2022	15	15	—	—	2	3	—	—	4	6	
12	14/11/2022	15	15	—	—	3	5	—	1	—	6	
13	15/11/2022	15	15	—	—	2	6	—	3	3	1	
14	16/11/2022	15	15	—	—	1	7	—	5	2	—	
15	17/11/2022	15	15	—	—	5	3	—	2	3	2	
16	18/11/2022	15	15	—	—	2	6	—	3	2	2	
17	19/11/2022	15	15	—	—	—	2	—	4	3	6	
18	21/11/2022	15	15	—	—	2	6	—	0	5	2	
19	22/11/2022	15	15	—	—	5	2	—	0	—	8	
20	23/11/2022	15	15	—	—	3	2	4	1	3	1	
21	24/11/2022	15	15	—	—	—	3	6	2	2	2	
22	25/11/2022	15	15	—	—	3	3	3	—	—	6	
23	26/11/2022	15	15	—	—	2	6	—	2	2	3	
24	28/11/2022	15	15	—	—	—	6	—	2	2	5	
25	29/11/2022	15	15	—	—	—	6	4	1	2	2	
26	30/11/2022	15	15	—	—	2	8	—	—	—	5	
27												
28		390	390			56	121	29	38	58	88	
29												
30												
31												

ASST. EXECUTIVE ENGINEER (E...
Bruhath Bangalore Mahanagara P...
Dasarahalli Zone, Bangalore

Scanned by CamScanner